

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2010 Levee Inspection Results**

Reclamation District No. 0784 Plumas Lake

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 01 Yuba River			Left	2.22

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/19/2010 - 4/19/2010			
DWR Inspector	Clay Thomas			
Accompanied By	Steve Fordice RD-784			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River						Left	2.22	04/19/2010 04/19/2010	Clay Thomas

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.04	2.21	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	39.134426 ° -121.552686 °	39.125935 ° -121.588624 °	2 Y
2	0.04	2.21	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	39.134426 ° -121.552686 °	39.125934 ° -121.588624 °	1 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.22	04/19/2010 04/19/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.04
End Levee Mile	2.21
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Water side vegetation levee mile 0.00.

cathom_s_20100520_070.jpg



Levee Mile Report Line	2
Start Levee Mile	0.04
End Levee Mile	2.21
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Land side vegetation levee mile 0.00.

cathom_s_20100520_069.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 02 Feather River			Left	13.64

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/19/2010 - 4/19/2010			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 Feather River						Left	13.64	04/19/2010 04/19/2010	Clay Thomas	

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.01	12.78	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	39.125613 ° -121.588671 °	38.955561 ° -121.575020 °	2 Y
2	0.01	12.78	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	39.125613 ° -121.588670 °	38.955561 ° -121.575020 °	1 Y
3	2.82	8.93	Earthen Levee	Encroachments	CR	A	Material Inspector Comments: new feather river setback levee north tie in L/M 2.82 the south tie in is at L/M 8.93, part of unit 2 has been degraded.	39.089592 ° -121.584917 °	39.010234 ° -121.579506 °	3

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	13.64	04/19/2010 04/19/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.01
End Levee Mile	12.78
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Water side vegetation levee mile 0.00.

cathom_s_20100520_072.jpg



Levee Mile Report Line	2
Start Levee Mile	0.01
End Levee Mile	12.78
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Land side vegetation levee mile 0.00.

cathom_s_20100520_071.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 03 Bear River			Right	4.73

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/19/2010 - 4/19/2010			
DWR Inspector	Clay Thomas			
Accompanied By	Steve Fordice			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 03 Bear River						Right	4.73	04/19/2010 04/19/2010	Clay Thomas	

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	2.44	3.20	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.970724 ° -121.547482 °	38.974683 ° -121.535296 °	2 Y
2	2.44	3.20	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.970725 ° -121.547482 °	38.974683 ° -121.535296 °	1 Y
3	2.82	2.82	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: hwy 70 new bridge construction	38.974003 ° -121.541910 °	38.974003 ° -121.541910 °	4

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Bear River	Right	4.73	04/19/2010 04/19/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	2.44
End Levee Mile	3.20
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Water side vegetation levee mile 2.44.

cathom_s_20100520_076.jpg



Levee Mile Report Line	2
Start Levee Mile	2.44
End Levee Mile	3.20
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Land side vegetation levee mile 2.44.

cathom_s_20100520_075.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 04 Interceptor Canal			Left	6.35
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/19/2010 - 4/19/2010			
DWR Inspector	Clay Thomas			
Accompanied By	Steve Fordice			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal						Left	6.35	04/19/2010 04/19/2010	Clay Thomas

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	5.86	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.974736 ° -121.535103 °	39.058587 ° -121.543129 °	2 Y
2	0.00	5.86	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.974737 ° -121.535102 °	39.058586 ° -121.543130 °	1 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal	Left	6.35	04/19/2010 04/19/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	5.86
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Water side vegetation levee mile 0.00.	
cathom_s_20100520_077.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	5.86
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Land side vegetation levee mile 0.00.	
cathom_s_20100520_078.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 05 Interceptor Canal			Left	4.20
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/19/2010 - 4/19/2010			
DWR Inspector	Clay Thomas			
Accompanied By	Steve Fordice RD 784			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 05 Interceptor Canal						Left	4.20	04/19/2010 04/19/2010	Clay Thomas	

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	3.87	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.974737 ° -121.532712 °	39.019481 ° -121.515068 °	1 Y
2	0.00	3.87	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.974737 ° -121.532711 °	39.019481 ° -121.515067 °	2 Y
3	1.08	1.72	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.989955 ° -121.535672 °	38.999068 ° -121.537462 °	10
4	2.10	3.06	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	39.004562 ° -121.538482 °	39.015593 ° -121.528533 °	9
5	3.88	4.20	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	39.019559 ° -121.514679 °	39.020574 ° -121.509016 °	11

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.20	04/19/2010 04/19/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	3.87
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Land side vegetation levee mile 3.87.

cathom_s_20100520_079.jpg



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	3.87
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Water side vegetation levee mile 3.87.

cathom_s_20100520_080.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 06 South Dry Creek			Right	1.50

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/19/2010 - 4/19/2010			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 06 South Dry Creek						Right	1.50	04/19/2010 04/19/2010	Clay Thomas

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.25	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.985550 ° -121.510470 °	38.987560 ° -121.506610 °	1
2	0.00	0.25	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.985550 ° -121.510470 °	38.987560 ° -121.506610 °	2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 07 Yuba River			Left	3.91

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/19/2010 - 4/19/2010			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 07 Yuba River						Left	3.91	04/19/2010 04/19/2010	Clay Thomas	

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.02	3.90	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	39.134789 ° -121.551839 °	39.165479 ° -121.495652 °	1 Y
2	0.02	3.90	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	39.134789 ° -121.551839 °	39.165479 ° -121.495652 °	2 Y
3	2.18	2.18	Earthen Levee	Encroachments	WS	CO	Buildings	39.149330 ° -121.518550 °	39.149330 ° -121.518550 °	4 Y
4	2.28	2.58	Supplemental	USACE Erosion Survey	WS	U	Inspector Comments: 2009: no berm, 1:1 slope, seepage, sands and silts, 0 ft/s [2009 SiteID:YUB_2-3_L]	39.153581 ° -121.513844 °	39.150442 ° -121.517481 °	5 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River	Left	3.91	04/19/2010 04/19/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.02
End Levee Mile	3.90
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Land side vegetation levee mile 3.91.

cathom_s_20100520_065.jpg



Levee Mile Report Line	2
Start Levee Mile	0.02
End Levee Mile	3.90
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Water side vegetation levee mile 3.91.

cathom_s_20100520_066.jpg



Levee Mile Report Line	3
Start Levee Mile	2.18
End Levee Mile	2.18
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Water side buildings and equipment levee mile 2.18.

cathom_s_20100520_067.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River	Left	3.91	04/19/2010 04/19/2010	Clay Thomas

Levee Mile Report Line	3
Start Levee Mile	2.18
End Levee Mile	2.18
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Water side buildings and equipment levee mile 2.18.	
cathom_s_20100520_068.jpg	



Levee Mile Report Line	4
Start Levee Mile	2.28
End Levee Mile	2.58
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
2009: no berm, 1:1 slope, seepage, sands and silts, 0 ft/s [2009 SiteID:YUB_2-3_L]	
USACE2009_YUB_2-3_L_2009_09_19-D5P3_small.JPG	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 08 Three Rivers				1.88
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/19/2010 - 4/19/2010			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 08 Three Rivers							1.88	04/19/2010 04/19/2010	Clay Thomas	

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.04	1.88	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.955523 ° -121.574250 °	38.970157 ° -121.547852 °	1 Y
2	0.04	1.88	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.955524 ° -121.574250 °	38.970157 ° -121.547852 °	2 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 08 Three Rivers		1.88	04/19/2010 04/19/2010	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.04
End Levee Mile	1.88
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Land side vegetation levee mile 0.00.

cathom_s_20100520_073.jpg



Levee Mile Report Line	2
Start Levee Mile	0.04
End Levee Mile	1.88
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Water side vegetation levee mile 0.00.

cathom_s_20100520_074.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected